

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |                   |          |
|-----------------|----------------------------------------|------|---------|-------------------|----------|
| INSPECTION DATE | 2025/10/27                             | MAKE | KOMATSU | MODEL             | PC40MR-2 |
| SERIAL          | 11244                                  |      | STAMP   | KMTPC092L05011244 |          |
| HR METER        | UNKNOWN                                |      | HR      | YEAR              | YR       |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 400G PADS         |          |

|                           |       |       |                                  |
|---------------------------|-------|-------|----------------------------------|
| ENGINE : MODEL            |       | 4D88E | S/N                              |
| Oil leakage               | FAIR  | Attn  |                                  |
| Blow-By                   | FAIR  | Attn  | A LITTLE · MIDDLE · SEVERE       |
| Sound                     | FAIR  | Attn  |                                  |
| Oil                       | FAIR  | Attn  |                                  |
| Exhaust Color             | FAIR  | Attn  |                                  |
| US EPA                    | YES   | NO    |                                  |
| MAIN PUMP                 |       |       |                                  |
| Sound                     | FAIR  | Attn  |                                  |
| Oil leakage               | FAIR  | Attn  |                                  |
| Power                     | FAIR  | Attn  |                                  |
| COOLING SYSTEM            |       |       |                                  |
| Radiator                  | FAIR  | Attn  |                                  |
| Oil Cooler                | FAIR  | Attn  |                                  |
| OPERATING SYSTEM          |       |       |                                  |
| Swing                     | FAIR  | Attn  | ゴリゴリ感あり RATTLING                 |
| Travel                    | FAIR  | Attn  | 増速S/W不良 HIGH SWITCH: MALFUNCTION |
| INTERIOR See Photos. 写真参照 |       |       |                                  |
| INTERIOR COND.            | CLEAN | FAIR  | DIRTY                            |
| Operator's Seat           | FAIR  | Attn  | 切れあり CUTS                        |
| Glasses                   | FAIR  | Attn  |                                  |
| AirCon                    | A/C   | H/C   | H only · C only · None           |
| BOOM / ARM / BKT          |       |       |                                  |
| Boom                      | FAIR  | Attn  |                                  |
| Boom Cylinder             | FAIR  | Attn  | 油にじみあり OIL OOZING                |
| Arm                       | FAIR  | Attn  |                                  |
| Arm Cylinder              | FAIR  | Attn  |                                  |
| ATTACHMENT                | FAIR  | Attn  | 穴あり、ガタあり HOLES, LOOSE            |
| BKT Cylinder              | FAIR  | Attn  |                                  |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。