

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/28	MAKE	IHI	MODEL	4J
SERIAL	AR003765			STAMP	AR003765
HR METER	1207	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>			SHOE	180R

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	油漏れ小 OIL LEAKING
Blow-By	FAIR ☒ Attn	A LITTLE ☐ MIDDLE ☐ SEVERE ☐
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	
Exhaust Color	FAIR ☒ Attn	
US EPA	YES ☐ <u>NO</u> ☒	
MAIN PUMP		
Sound	FAIR ☒ Attn	
Oil leakage	FAIR ☒ Attn	
Power	FAIR ☒ Attn	
COOLING SYSTEM		
Radiator	FAIR ☒ Attn	
Oil Cooler	FAIR ☒ Attn	
OPERATING SYSTEM		
Swing	FAIR ☒ Attn	ガタあり SWING: LOOSE
Travel	FAIR ☒ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ☐ <u>FAIR</u> ☒ DIRTY ☐	
Operator's Seat	FAIR ☒ Attn	ガタ小 LOOSE
Glasses	FAIR ☒ Attn	
AirCon	A/C ☐ H/C ☐ H only ☐ C only ☐ <u>None</u> ☒	
BOOM / ARM / BKT		
Boom	FAIR ☒ Attn	
Boom Cylinder	FAIR ☒ Attn	サビあり RUSTY
Arm	FAIR ☒ Attn	
Arm Cylinder	FAIR ☒ Attn	油漏れあり OIL LEAKING
ATTACHMENT	FAIR ☒ Attn	
BKT Cylinder	FAIR ☒ Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	<u>STD</u> ☒ SLOPE ☐ NARROW ☐ SKELETON ☐ OTHER () ☐
Lever	LONG ☐ <u>WRIST</u> ☒
Multi	MULTI ☐ <u>2</u> ☒ NO ☐
ARM-CRANE	YES ☐ <u>NO</u> ☒
BLADE	<u>YES</u> ☒ NO ☐
OFFSET	YES ☐ <u>NO</u> ☒
OFFSET Cylinder	FAIR ☒ Attn
Piping	YES ☐ <u>NO</u> ☒ Breaker only ☐ Multi ☐
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。