

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/11/27	MAKE	HITACHI	MODEL	ZX120-3
SERIAL	HCM1R100E00094105		STAMP	HCM1R100E00094105	
HR METER	9546	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL 4JJ1 S/N 164470	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
MAIN PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
OPERATING SYSTEM	
Swing	FAIR · Attn
Travel	FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn 切れあり HUGE CUTS
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	FAIR · Attn
Boom Cylinder	FAIR · Attn
Arm	FAIR · Attn スライドアーム SLIDE ARM
Arm Cylinder	FAIR · Attn
ATTACHMENT	FAIR · Attn 改造あり、摩耗あり MODIFIED, WORN
BKT Cylinder	FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。