

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/11/19	MAKE	CAT	MODEL	312D
SERIAL	NO PLATE		STAMP	CAT0312DEFBJ01592	
HR METER	5244	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE : MODEL C4.2 S/N JKH12518 Oil leakage ☒ FAIR · Attn Blow-By ☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE Sound ☒ FAIR · Attn Oil ☒ FAIR · Attn Exhaust Color ☒ FAIR · Attn US EPA ☒ YES · NO MAIN PUMP Sound ☒ FAIR · Attn Oil leakage ☒ FAIR · Attn Power ☒ FAIR · Attn COOLING SYSTEM Radiator ☒ FAIR · Attn Oil Cooler ☒ FAIR · Attn OPERATING SYSTEM Swing ☒ FAIR · Attn ガタあり SWING: LOOSE Travel ☒ FAIR · Attn INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · FAIR · ☒ DIRTY Operator's Seat FAIR · ☒ Attn 破れ大、汚れあり CUTS, DIRTY Glasses ☒ FAIR · Attn AirCon ☒ A/C · H/C · H only · C only · None BOOM / ARM / BKT Boom ☒ FAIR · Attn Boom Cylinder FAIR · ☒ Attn *1 Arm ☒ FAIR · Attn ロングアーム LONG ARM Arm Cylinder ☒ FAIR · Attn ATTACHMENT ☒ FAIR · Attn ガタあり LOOSE BKT Cylinder ☒ FAIR · Attn	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3 COMMENT BKT ☒ STD / ☐ SLOPE / ☐ NARROW / ☐ SKELETON / OTHER () Lever LONG · ☒ WRIST Multi ☒ MULTI · 2 · NO ARM-CRANE YES · ☒ NO BLADE YES · ☒ NO OFFSET YES · ☒ NO OFFSET Cylinder FAIR · Attn Piping ☒ YES · NO Breaker only · Multi *2 COMMENT モニター: HR表示見えない、燃料レベル低い表示消えない HR METER ON MONITOR: NOT DISPLAYING, WARNING DISPLAY FOR LOW FUEL LEVEL: NOT DISAPPEARING コントロールバルブ付近にじみあり(吸着マットあり) AROUND CONTROL VALVE: OIL OOZING (W/ABSORPTION MAT) *1 左油漏れ、右にじみあり(左右吸着マットあり) *1 LEFT CYLINDER: OIL LEAKING, RIGHT CYLINDER: OIL OOZING (CYLINDERS: W/ABSORPTION MATS) *2 右操作レバー: 設定切替らない *2 UNABLE TO OPERATE BY SWITCH AT THE RIGHT OPERATION LEVER GRIP RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
--	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。