

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/12/15	MAKE	KATO	MODEL	HD308US-7
SERIAL	KWJ58E01HK0005146			STAMP	5146
HR METER	2419 / UNKNOWN	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	450G PADS

ENGINE : MODEL 4TNV98C S/N	UNDERCARRIAGE : See Photos. 写真参照
Oil leakage FAIR · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
Blow-By FAIR · Attn A LITTLE · MIDDLE · SEVERE	COMMENT
Sound FAIR · Attn	
Oil FAIR · Attn	
Exhaust Color FAIR · Attn	
US EPA YES · NO	
MAIN PUMP	BKT STD / SLOPE / NARROW / SKELETON / OTHER ()
Sound FAIR · Attn	Lever LONG · WRIST
Oil leakage FAIR · Attn	Multi MULTI · 2 · NO
Power FAIR · Attn	ARM-CRANE YES · NO
COOLING SYSTEM	BLADE YES · NO
Radiator FAIR · Attn	OFFSET YES · NO
Oil Cooler FAIR · Attn	OFFSET Cylinder FAIR · Attn
OPERATING SYSTEM	Piping YES · NO Breaker only Multi
Swing FAIR · Attn	COMMENT
Travel FAIR · Attn	A/Cモニター下の送風口から風が出ない
INTERIOR See Photos. 写真参照	A/C: NOT BLOWING AIR FROM THE AIR OUTLET UNDER MONITOR
INTERIOR COND. CLEAN · FAIR · DIRTY	下側HRメーター不良 ONE OF HR METERS: MALFUNCTION
Operator's Seat FAIR · Attn	
Glasses FAIR · Attn	
AirCon A/C · H/C · H only · C only · None	
BOOM / ARM / BKT	
Boom FAIR · Attn	
Boom Cylinder FAIR · Attn	
Arm FAIR · Attn	
Arm Cylinder FAIR · Attn	
ATTACHMENT FAIR · Attn	
BKT Cylinder FAIR · Attn	
	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。