

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/11/20	MAKE	KOMATSU	MODEL	PC200-3
SERIAL	25650			STAMP	PC200-25650
HR METER	18126	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	610G

ENGINE : MODEL S/N Oil leakage FAIR ☒ Attn *1 Blow-By FAIR ☒ Attn A LITTLE · MIDDLE · SEVERE Sound ☒ FAIR · Attn Oil ☒ FAIR · Attn Exhaust Color ☒ FAIR · Attn US EPA YES ☒ NO MAIN PUMP Sound ☒ FAIR · Attn Oil leakage ☒ FAIR · Attn Power ☒ FAIR · Attn COOLING SYSTEM Radiator ☒ FAIR · Attn Oil Cooler ☒ FAIR · Attn OPERATING SYSTEM Swing ☒ FAIR · Attn ガタあり SWING: LOOSE Travel FAIR ☒ Attn 前後右へ寄る TOTTERING TO RIGHT INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · FAIR · DIRTY Operator's Seat FAIR ☒ Attn 破れ大 TORN Glasses ☒ FAIR · Attn AirCon A/C · H/C · H only · C only · None BOOM / ARM / BKT Boom ☒ FAIR · Attn ガタあり LOOSE Boom Cylinder FAIR ☒ Attn *2 Arm ☒ FAIR · Attn *3 Arm Cylinder FAIR ☒ Attn *4 ATTACHMENT ☒ FAIR · Attn ガタあり LOOSE BKT Cylinder ☒ FAIR · Attn	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3 COMMENT BKT ☒ STD / ☐ SLOPE / ☐ NARROW / ☐ SKELETON / OTHER () Lever ☒ LONG · ☐ WRIST Multi MULTI · 2 · ☒ NO ARM-CRANE YES ☒ NO BLADE YES ☒ NO OFFSET YES ☒ NO OFFSET Cylinder FAIR · Attn Piping ☒ YES · ☐ NO ☒ Breaker only · Multi COMMENT 機体外装リペイントあり REPAINTED A/Cベルト欠、A/C故障あり A/C: NO BELT, MALFUNCTION E/Gからの下周り油漏れあり BOTTOM OF ENGINE PART: OIL LEAKING *1 E/G周り油漏れ多数あり AROUND ENGINE: MUCH OIL LEAKING *2 右油漏れあり(吸着マット付) *2 RIGHT CYLINDER: OIL LEAKING (W/ABSORPTION MAT) *3 ガタ、パッチ、クラックあり LOOSE, PATCHED, CRACKED *4 油漏れあり(吸着マット付) OIL LEAKING (W/ABSORPTION MAT) RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2
---	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。