

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/12/22	MAKE	KOMATSU	MODEL	LW500-1
SERIAL No.	PLATE : 10054			STAMP : L005-10054	
HR METER	4306	HR	Odometer	4427	km
TIRE SIZE	505/95R25			YEAR	2003 YR

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Computer	<input checked="" type="radio"/> OK · NG *1	
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
TRANSMISSION		
Transmission	<input checked="" type="radio"/> FAIR · Attn	
No. OF GEARS	3 GEARS	
4WD	<input checked="" type="radio"/> 4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
COMMENT		

BOOM				
No. of Section	6	SECTIONS		
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR · Attn			
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · Attn			
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · Attn			
JIB	YES · <input checked="" type="radio"/> NO			
JIB TYPE	STD · PWR			
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO			
FREE FALL	<input checked="" type="radio"/> YES · NO			
HOOK	50t, 25t, BALL			
UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)				1
TIRE WEAR		<input checked="" type="radio"/> FAIR · WORN · UNEVEN WEAR		
COMMENT				
右F、左Rサスシリンダーにじみあり				
FRONT RIGHT & REAR LEFT SUSPENSION CYLINDERS: OIL OOZING				
OUTRIGGERS				
OUTRIGGERS	X · <input checked="" type="radio"/> H			
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR · Attn			
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R
COMMENT				
付属品:リモコン(動作未確認) REMOTO CONTROL (OPERATION NOT CONFRIMED)				
*1 ML画面映り悪くて設定できない、ML解除で操作可				
*1 UNABLE TO SET UP (MONITOR: BLURRED),				
NEED TO CUT THE COMPUTER TO OPERATE				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。