

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/1/19	MAKE	mitsubishi	MODEL	BD2G
SERIAL	2B100325		STAMP	2B100325	
HR METER	2693	HR	SHOE	500LGP	YEAR YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL		S/N	65003
Oil leakage	FAIR • (Attn)	にじみあり OIL OOZING	
Blow-By	(FAIR) • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	(FAIR) • Attn		
Oil	(FAIR) • Attn		
Exhaust Color	(FAIR) • Attn		
US EPA	YES • (NO)		
OPERATION PUMP			
Sound	(FAIR) • Attn		
Oil leakage	(FAIR) • Attn		
Power	(FAIR) • Attn		
COOLING SYSTEM			
Radiator	(FAIR) • Attn		
Oil Cooler	(FAIR) • Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	(PS) • DD	DIFF. STEERING	YES • (NO)
Transmission	(FAIR) • Attn		
Travel	(FAIR) • Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • (FAIR) • DIRTY		
Operator's Seat	(FAIR) • Attn	破れあり HUGE CUT	
Glasses	FAIR • Attn		
AirCon	A/C • H/C • H only • C only • (None)		
BLADE & CYLINDERS			
BLADE	(FAIR) • Attn		
CYLD.(R)	(FAIR) • Attn		
CYLD.(L)	(FAIR) • Attn		
TILT CYLD	(FAIR) • Attn		
ANGLE CYLD	FAIR • (Attn)	*1	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
COMMENT			
Ripper MULTI • S/S Shanks PCS			
Ripper CYLD. FAIR • Attn			
COMMENT			
バッテリーランプ点灯あり BATTERY WARNING LAMP: ON 燃料メーター不良 FUEL GAUGE: MALFUNCTION *1 左右にじみ、傷あり CYLINDERS: OIL OOZING, SCRACHED			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2			

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。