

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/12/12	MAKE	CAT	MODEL	320CL
SERIAL	CAT0320CHGAA00240		STAMP	CAT0320CHGAA00240	
HR METER	12747	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	800G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	油漏れあり OIL LEAKING
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	ガタあり LOOSE
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	にじみあり OIL OOOZING

UNDERCARRIAGE :						See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)										3	
COMMENT											
右走行モーター油漏れあり RIGHT TRAVEL MOTOR: OIL LEAKING											
トラックローラー不良多数あり MANY TRACK ROLLERS: MALFUNCTION											
BKT		(STD / SLOPE / NARROW / SKELETON / OTHER())									
Lever		LONG ▪		(WRIST)							
Multi		MULTI ▪ 2 ▪		(NO)							
ARM-CRANE		YES ▪		(NO)							
BLADE		YES ▪		(NO)							
OFFSET		YES ▪		(NO)							
OFFSET Cylinder		FAIR ▪ Attn									
Piping		YES ▪		(NO) Breaker only ▪ Multi							
COMMENT											
15.2mスーパーロング 15.2m SUPER LONG											
底板油污れあり BOTTOM: OIL STAINS											
右側操作レバー周り油漏れあり											
AROUND RIGHT OPERATION LEVER: OIL LEAKING											
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)										3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。