

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/11/27	MAKE	HITACHI	MODEL	ZW80-5B
SERIAL	RYUNCHA0E00012389			STAMP	H80-12389
HR METER	3248	HR	Odometer	6967	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	17.5/65-20

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
US EPA	YES · ☒ NO	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	☒ PS · DD	
Transmission	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
FOOT BRAKE	☒ FAIR · Attn	
PARKING BRAKE	☒ FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY	
Operator's Seat	☒ FAIR · Attn	破れあり CUT
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	
FRONT & CYLINDERS		
Arm	☒ FAIR · Attn	
Bell crank	☒ FAIR · Attn	
Bucket	☒ FAIR · Attn	
Articulate	☒ FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	YES · ☒ NO
ATTACHMENTS	
STD BKT	☒ YES · OTHER
BLADE	YES · ☒ NO Piping for Tilt YES · ☒ NO
COMMENT	
E/G周りホース冷却水漏れ小	
SOME HOSE AROUND ENGINE: COOLANT LEAKING	
E/Gフード割れあり ENGINE HOOD: CRACKED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。