

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/19	MAKE	KOBELCO	MODEL	SK135SR
SERIAL	YY07-27953		STAMP	YY07-27953	
HR METER	3025	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	にじみあり OIL OOOZING
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	油漏れあり OIL LEAKING
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE :						See Photos. 写真参照						
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)									4			
COMMENT												
BKT	STD / SLOPE / NARROW / SKELETON								(OTHER)		FORK GRAB)	
Lever	LONG		▪		(WRIST)							
Multi	(MULTI)		▪		2		▪		NO			
ARM-CRANE	YES		▪		(NO)							
BLADE	(YES)		▪		NO							
OFFSET	YES		▪		(NO)							
OFFSET Cylinder	FAIR		▪		Attn							
Piping	(YES)		▪		NO		Breaker only		▪		Multi 3 *1	
COMMENT												
排気ガス後処理装置メンテナンス表示あり												
WARNING DISPLAY												
FOR EXHAUST AFTERTREATMENT SYSTEM MAINTENANCE												
*1 油圧起きない、メクラ2箇所油漏れあり												
*1 UNABLE TO SUPPLY ANY HYDRAULIC PRESSURE,												
2 OF CAPS: OIL LEAKING												
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)										4		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。