

INSPECTION SHEET 検品書

OTHER その他

INSPECTION DATE		2025/11/20		CATEGORY		WOOD CRUSHER				
MAKE	PRECISION HUSKY				MODEL	KBLR4000				
SERIAL	PG163				STAMP	NOT FOUND				
HR METER	5936		HR	Odometer			km	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE				SHOE			TIRE	215/70R17.5	

ENGINE	MODEL	C-15	S/N	BEM00608		
Oil leakage	FAIR	Attn	*1	Oil	FAIR	Attn
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE	Exhaust Color	FAIR	Attn
Sound	FAIR	Attn		EPA	YES	NO

CONDITION	FAIR	Attn
ラジエータ水少ない、錆びあり RADIATOR: NOT ENOUGH WATER, RUSTY		

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR WORN ・ UNEVEN WEAR
COMMENT			
コンベアシリンダー(左前)油漏れ小 CONVEYOR CYLINDER (FRONT LEFT): OIL LEAKING			
アウトリガーシリンダーメッキはがれあり PLATING OF OUTRIGGER CYLINDER: PEELED OFF			
オールリペイントあり ALL REPAINTED			
リモコン付き W/REMOTE CONTROL			
コンプレッサー付き (PDS70S-5061431 2862HRS ラジエータ水入ってない)			
W/COMPRESSOR (PDS70S-5061432 2862HRS RADIATOR: NO WATER)			
*1 オイルパンドレン付近油にじみあり AROUND OIL PAN DRAIN: OIL OOZING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。