

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |      |       |                   |
|-----------------|----------------------------------------|------|------|-------|-------------------|
| INSPECTION DATE | 2026/1/15                              | MAKE | CAT  | MODEL | 313CSR            |
| SERIAL          | CAT0313CKWSA00275                      |      |      | STAMP | CAT0313CKWSA00275 |
| HR METER        | E3371                                  | HR   | YEAR | YR    |                   |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |      | SHOE  | 500G PADS         |

|                           |                                    |                                 |          |
|---------------------------|------------------------------------|---------------------------------|----------|
| ENGINE : MODEL            |                                    | S/N                             | 6LK29163 |
| Oil leakage               | FAIR · Attn                        |                                 |          |
| Blow-By                   | FAIR · Attn                        | A LITTLE · MIDDLE · SEVERE      |          |
| Sound                     | FAIR · Attn                        |                                 |          |
| Oil                       | FAIR · Attn                        |                                 |          |
| Exhaust Color             | FAIR · Attn                        |                                 |          |
| US EPA                    | YES · NO                           |                                 |          |
| MAIN PUMP                 |                                    |                                 |          |
| Sound                     | FAIR · Attn                        |                                 |          |
| Oil leakage               | FAIR · Attn                        |                                 |          |
| Power                     | FAIR · Attn                        |                                 |          |
| COOLING SYSTEM            |                                    |                                 |          |
| Radiator                  | FAIR · Attn                        |                                 |          |
| Oil Cooler                | FAIR · Attn                        |                                 |          |
| OPERATING SYSTEM          |                                    |                                 |          |
| Swing                     | FAIR · Attn                        | ガタあり SWING: LOOSE               |          |
| Travel                    | FAIR · Attn                        |                                 |          |
| INTERIOR See Photos. 写真参照 |                                    |                                 |          |
| INTERIOR COND.            | CLEAN · FAIR · DIRTY               |                                 |          |
| Operator's Seat           | FAIR · Attn                        | 破れあり TORN                       |          |
| Glasses                   | FAIR · Attn                        | F割れあり UPPER WINDSHIELD: CRACKED |          |
| AirCon                    | A/C · H/C · H only · C only · None |                                 |          |
| BOOM / ARM / BKT          |                                    |                                 |          |
| Boom                      | FAIR · Attn                        |                                 |          |
| Boom Cylinder             | FAIR · Attn                        | *1                              |          |
| Arm                       | FAIR · Attn                        | ガタあり LOOSE                      |          |
| Arm Cylinder              | FAIR · Attn                        |                                 |          |
| ATTACHMENT                | FAIR · Attn                        | *2                              |          |
| BKT Cylinder              | FAIR · Attn                        |                                 |          |

|                                                                      |         |   |         |              |        |   |                    |             |  |
|----------------------------------------------------------------------|---------|---|---------|--------------|--------|---|--------------------|-------------|--|
| <b>UNDERCARRIAGE :</b>                                               |         |   |         |              |        |   | <b>See Photos.</b> | <b>写真参照</b> |  |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         |         |   |         |              |        |   |                    | 3           |  |
| <b>COMMENT</b>                                                       |         |   |         |              |        |   |                    |             |  |
|                                                                      |         |   |         |              |        |   |                    |             |  |
|                                                                      |         |   |         |              |        |   |                    |             |  |
|                                                                      |         |   |         |              |        |   |                    |             |  |
|                                                                      |         |   |         |              |        |   |                    |             |  |
| BKT                                                                  | (STD)   | / | SLOPE   | /            | NARROW | / | SKELETON           | / OTHER( )  |  |
| Lever                                                                | LONG    | ▪ | (WRIST) |              |        |   |                    |             |  |
| Multi                                                                | (MULTI) | ▪ | 2       | ▪            | NO     |   |                    |             |  |
| ARM-CRANE                                                            | (YES)   | ▪ | NO      |              |        |   |                    |             |  |
| BLADE                                                                | (YES)   | ▪ | NO      |              |        |   |                    |             |  |
| OFFSET                                                               | (YES)   | ▪ | NO      |              |        |   |                    |             |  |
| OFFSET Cylinder                                                      | (FAIR)  | ▪ | Attn    |              |        |   |                    |             |  |
| Piping                                                               | YES     | ▪ | (NO)    | Breaker only |        | ▪ | Multi              |             |  |
| <b>COMMENT</b>                                                       |         |   |         |              |        |   |                    |             |  |
| HRメーターストップ HR METER: STOPPED                                         |         |   |         |              |        |   |                    |             |  |
| ブーム背面ホース破れあり SOME HOSE AROUND BOOM: CUT                              |         |   |         |              |        |   |                    |             |  |
| *1 左側にじみ、右側油漏れあり                                                     |         |   |         |              |        |   |                    |             |  |
| *1 LEFT CYLINDER: OIL OOZING, RIGHT CYLINDER: OIL LEAKING            |         |   |         |              |        |   |                    |             |  |
| *2 ピンロックボルト欠、ガタあり SOME PIN LOCK BOLT: MISSING, LOOSE                 |         |   |         |              |        |   |                    |             |  |
|                                                                      |         |   |         |              |        |   |                    |             |  |
|                                                                      |         |   |         |              |        |   |                    |             |  |
|                                                                      |         |   |         |              |        |   |                    |             |  |
|                                                                      |         |   |         |              |        |   |                    |             |  |
|                                                                      |         |   |         |              |        |   |                    |             |  |
|                                                                      |         |   |         |              |        |   |                    |             |  |
|                                                                      |         |   |         |              |        |   |                    |             |  |
|                                                                      |         |   |         |              |        |   |                    |             |  |
|                                                                      |         |   |         |              |        |   |                    |             |  |
|                                                                      |         |   |         |              |        |   |                    |             |  |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) |         |   |         |              |        |   |                    | 3           |  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。