

INSPECTION SHEET 検品書
ASPHALT FINISHER アスファルトフィニッシャー

INSPECTION DATE	2025/12/5	MAKE	SUMITOMO	MODEL	HA60C
SERIAL	HA60C-0411			STAMP	HA60C-0411
HR METER	1233	HR	YEAR	YR	
SHOE	280G PADS	TIRE (REAR)	MAX PAVING WIDTH		4800 mm

ENGINE : MODEL		S/N	
Oil leakage	FAIR・Attn		
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE	
Sound	FAIR・Attn		
Oil	FAIR・Attn		
Exhaust Color	FAIR・Attn		
US EPA	YES・NO		
OPERATION PUMP			
Sound	FAIR・Attn		
Oil leakage	FAIR・Attn		
Power	FAIR・Attn		
COOLING SYSTEM			
Radiator	FAIR・Attn		
Oil Cooler	FAIR・Attn		
OPERATING SYSTEM			
TRAVEL	FAIR・Attn	*1	
SCREED(R)	FAIR・Attn	*2	
SCREED(L)	FAIR・Attn	*3	
VIBRATION	FAIR・Attn		
TAMPER	FAIR・Attn		
SPREADER(R)	FAIR・Attn		
SPREADER(L)	FAIR・Attn		
HOPPER(R)	FAIR・Attn		
HOPPER(L)	FAIR・Attn	シリンダーにじみあり CYLINDER: OIL OOZING	
FEEDER	FAIR・Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	
TIRE WEAR	FAIR・WORN・UNEVEN WEAR
COMMENT	
SCREED WIDTH	
MAIN SCREED	2.8 m
WITH AUTO-WIDENER	4.8 m
WITH EXTENSION	m
LEVEL SENSOR	YES・NO
COMMENT	
CNP	
シートガタあり SEAT: LOOSE	
エアクリーナー、水量ランプ点灯あり	
WARNING LAMPS FOR AIR CLEANER & COOLANT LEVEL: ON	
*1 走行中異常ランプ点滅あり WARNING LAMP: BLINKED	
*2 伸縮シリンダー傷あり EXTENSION CYLINDER: SCRATCHED	
*3 リフトシリンダーにじみ、伸縮シリンダー傷あり	
*3 LIFT CYLINDER: OIL OOZING, EXTENSION CYLINDER: SCRACHED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。