

**INSPECTION SHEET 検品書**  
**CRAWLER CRANE クローラクレーン**

INSPECTION DATE	2025/11/27	MAKE	KOBELCO	MODEL	7045-1E
SERIAL No.	PLATE :	GM01-00489		STAMP	GM01-00489 (HARD TO READ)
HR METER	11822	HR	SHOE	760FLAT	YEAR
YR					
<b>ENGINE : MODEL</b> <b>S/N</b>				<b>INTERIOR</b> See Photos. 写真参照	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn			INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE		Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Sound	<input checked="" type="radio"/> FAIR · Attn			Glasses	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn			AirCon	A/C · <input checked="" type="radio"/> H/C · H only · C only · None
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn			<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
<b>OPERATION PUMP</b>				RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 1	
Sound	<input checked="" type="radio"/> FAIR · Attn			<b>COMMENT</b> 左右キャタたるみあり TRACK LINKS: WORN	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn				
Power	<input checked="" type="radio"/> FAIR · Attn				
<b>COOLING SYSTEM</b>				WEIGHT	3
Radiator	<input checked="" type="radio"/> FAIR · Attn			HOOK	45t, 25t, BALL
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn			FREE FALL	<input checked="" type="radio"/> YES · NO 操作できない NOT WORKING
<b>OPERATING SYSTEM</b>				LIFTER	<input checked="" type="radio"/> YES · NO
Computer	<input checked="" type="radio"/> OK · NG	未確認 NOT CHECKED		<b>COMMENT</b> ワイヤーソケットピン2本欠 2 WIRE ROPE SOCKET PINS: MISSING	
Swing	<input checked="" type="radio"/> FAIR · Attn				
Travel	<input checked="" type="radio"/> FAIR · Attn			CAB穴あり CAB: HUGE HOLES	
<b>BOOM</b>				本体左右扉開かない SOME SIDE COVERS: UNABLE TO OPEN	
MAIN BOOM	TOP, BOTTOM, 9m × 1, 6m × 2, 3m × 1			レバー固着のため起伏操作注意	
BOOM TOTAL	33m			ATTENTION TO BOOM LUFFING OPERATION (OPERATION LEVER: STUCK)	
TOP SHEAVE	<input checked="" type="radio"/> YES · NO			@NARITA YARD	
JIB				BOOM: TOP, BOTTOM, 6m × 1, 45t HOOK	
TOWER				@SAKURA YARD	
				BOOM: 9m × 1, 6m × 1, 3m × 1, HOOK: 25t, BALL	
				RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。