

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/12/4	MAKE	KOMATSU	MODEL	PC220LC-8N1
SERIAL	80281		STAMP	KMTPC198C02080281	
HR METER	4184	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G PADS	

ENGINE :		MODEL	6D107E-1	S/N	26527845
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
MAIN PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Swing	FAIR	Attn			
Travel	FAIR	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN · FAIR · DIRTY				
Operator's Seat	FAIR	Attn			
Glasses	FAIR	Attn			
AirCon	A/C · H/C · H only · C only · None				
BOOM / ARM / BKT					
Boom	FAIR	Attn			
Boom Cylinder	FAIR	Attn			
Arm	FAIR	Attn			
Arm Cylinder	FAIR	Attn			
ATTACHMENT	FAIR	Attn			
BKT Cylinder	FAIR	Attn			

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	STD / SLOPE / NARROW / SKELETON / OTHER(MAGNET)	
Lever	LONG ▪ WRIST	
Multi	MULTI ▪ 2 ▪ NO	
ARM-CRANE	YES ▪ NO	
BLADE	YES ▪ NO	
OFFSET	YES ▪ NO	
OFFSET Cylinder	FAIR ▪ Attn	
Piping	(YES) ▪ NO	Breaker only ▪ Multi
COMMENT		
MAGNET MAKE: SHINKO LMCH-130HA-6-V600360106 発電機あり(バッテリー上がりあり、油脂類OK、HRメーター: 5246) W/GENERATOR (BATTERY: RUN OUT, OIL: OK, HR METER: 5246) 付属品: 回転式カッター ROTATABLE CUTTER (MAKE: SAKATO VIP2200-PF00274) AS SPARE 		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。