

INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2025/12/17	MAKE	UNI CARRIERS	MODEL	FD30T5M
SERIAL	F202-01741		STAMP	F202-01741	
HR METER	9898	HR	Odometer	-	km
CAB/CNP	CAB	/	CNP	/	NONE
TIRE SIZE	F: 28 × 9-15/7.00 R: 6.50-10/5.00				
MAX LIFTING HEIGHT	4.0	m	VIEW	MONO	
FORK LENGTH	1070 mm				
FORK SPEC	サイドシフト SIDE-SHIFT				

ENGINE : MODEL S/N <table style="width: 100%;"> <tr> <td style="width: 15%;">Oil leakage</td> <td style="width: 10%;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Blow-By</td> <td>FAIR</td> <td>Attn</td> <td>A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Oil</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Exhaust Color</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>US EPA</td> <td>YES</td> <td>NO</td> <td></td> </tr> </table> OPERATION PUMP <table style="width: 100%;"> <tr> <td style="width: 15%;">Sound</td> <td style="width: 10%;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Oil leakage</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Power</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> </table> COOLING SYSTEM <table style="width: 100%;"> <tr> <td style="width: 15%;">Radiator</td> <td style="width: 10%;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>Oil Cooler</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> </table> TRANSMISSION & TRAVEL <table style="width: 100%;"> <tr> <td style="width: 15%;">T/M TYPE</td> <td style="width: 10%;">PS</td> <td style="width: 10%;">DD</td> <td style="width: 65%;"></td> </tr> <tr> <td>Transmission</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Travel</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>FOOT BRAKE</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>PARKING BRAKE</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> </table> INTERIOR See Photos. 写真参照 <table style="width: 100%;"> <tr> <td style="width: 15%;">INTERIOR COND.</td> <td style="width: 10%;">CLEAN</td> <td style="width: 10%;">FAIR</td> <td style="width: 65%;">DIRTY</td> </tr> <tr> <td>Operator's Seat</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>Glasses</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> <tr> <td>AirCon</td> <td>A/C</td> <td>H/C</td> <td>H only · C only · None</td> </tr> </table> HYDRAULICS <table style="width: 100%;"> <tr> <td style="width: 15%;">MAST Cylinder</td> <td style="width: 10%;">FAIR</td> <td style="width: 10%;">Attn</td> <td style="width: 65%;"></td> </tr> <tr> <td>TILT Cylinder</td> <td>FAIR</td> <td>Attn</td> <td></td> </tr> </table>	Oil leakage	FAIR	Attn		Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	Sound	FAIR	Attn		Oil	FAIR	Attn		Exhaust Color	FAIR	Attn		US EPA	YES	NO		Sound	FAIR	Attn		Oil leakage	FAIR	Attn		Power	FAIR	Attn		Radiator	FAIR	Attn		Oil Cooler	FAIR	Attn		T/M TYPE	PS	DD		Transmission	FAIR	Attn		Travel	FAIR	Attn		FOOT BRAKE	FAIR	Attn		PARKING BRAKE	FAIR	Attn		INTERIOR COND.	CLEAN	FAIR	DIRTY	Operator's Seat	FAIR	Attn		Glasses	FAIR	Attn		AirCon	A/C	H/C	H only · C only · None	MAST Cylinder	FAIR	Attn		TILT Cylinder	FAIR	Attn		UNDERCARRIAGE : See Photos. 写真参照 <table style="width: 100%;"> <tr> <td style="width: 85%;">RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="width: 15%;">3</td> </tr> <tr> <td>TIRE WEAR</td> <td>FAIR · WORN · UNEVEN WEAR</td> </tr> </table> COMMENT	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR · WORN · UNEVEN WEAR
Oil leakage	FAIR	Attn																																																																																											
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE																																																																																										
Sound	FAIR	Attn																																																																																											
Oil	FAIR	Attn																																																																																											
Exhaust Color	FAIR	Attn																																																																																											
US EPA	YES	NO																																																																																											
Sound	FAIR	Attn																																																																																											
Oil leakage	FAIR	Attn																																																																																											
Power	FAIR	Attn																																																																																											
Radiator	FAIR	Attn																																																																																											
Oil Cooler	FAIR	Attn																																																																																											
T/M TYPE	PS	DD																																																																																											
Transmission	FAIR	Attn																																																																																											
Travel	FAIR	Attn																																																																																											
FOOT BRAKE	FAIR	Attn																																																																																											
PARKING BRAKE	FAIR	Attn																																																																																											
INTERIOR COND.	CLEAN	FAIR	DIRTY																																																																																										
Operator's Seat	FAIR	Attn																																																																																											
Glasses	FAIR	Attn																																																																																											
AirCon	A/C	H/C	H only · C only · None																																																																																										
MAST Cylinder	FAIR	Attn																																																																																											
TILT Cylinder	FAIR	Attn																																																																																											
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3																																																																																												
TIRE WEAR	FAIR · WORN · UNEVEN WEAR																																																																																												
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3																																																																																													

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。