

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/12/1	MAKE	KOMATSU	MODEL	PC27MR-2
SERIAL	15280			STAMP	KMTPC120E05015280
HR METER	2544	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE			SHOE	300R

ENGINE : MODEL		S/N
Oil leakage	<u>FAIR</u> ・ Attn	
Blow-By	<u>FAIR</u> ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	<u>FAIR</u> ・ Attn	
Oil	<u>FAIR</u> ・ Attn	
Exhaust Color	<u>FAIR</u> ・ Attn	
US EPA	<u>YES</u> ・ NO	
MAIN PUMP		
Sound	<u>FAIR</u> ・ Attn	
Oil leakage	<u>FAIR</u> ・ Attn	
Power	<u>FAIR</u> ・ Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> ・ Attn	
Oil Cooler	<u>FAIR</u> ・ Attn	
OPERATING SYSTEM		
Swing	<u>FAIR</u> ・ Attn	
Travel	<u>FAIR</u> ・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ <u>FAIR</u> ・ DIRTY	
Operator's Seat	<u>FAIR</u> ・ Attn	破れあり HUGE CUTS
Glasses	FAIR ・ Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・ <u>None</u>	
BOOM / ARM / BKT		
Boom	<u>FAIR</u> ・ Attn	
Boom Cylinder	<u>FAIR</u> ・ Attn	
Arm	<u>FAIR</u> ・ Attn	
Arm Cylinder	<u>FAIR</u> ・ Attn	
ATTACHMENT	<u>FAIR</u> ・ Attn	
BKT Cylinder	<u>FAIR</u> ・ Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG ・ <u>WRIST</u>
Multi	MULTI ・ 2 ・ <u>NO</u>
ARM-CRANE	YES ・ <u>NO</u>
BLADE	<u>YES</u> ・ NO
OFFSET	YES ・ <u>NO</u>
OFFSET Cylinder	FAIR ・ Attn
Piping	YES ・ <u>NO</u> Breaker only ・ Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。