

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/12/17	MAKE	CAT	MODEL	312
SERIAL	7DK04855		STAMP	7DK04855	
HR METER	7508	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	F上部ひび割れあり UPPER WINDSHIELD: CRACKED
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	両側油漏れあり CYLINDERS: OIL LEAKING
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	油漏れあり OIL LEAKING

UNDERCARRIAGE :						See Photos.						写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																1	
COMMENT 両側トラックローラー不良あり SOME TRACK ROLLERS: MALFUNCTION 																	
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()																
Lever	LONG ▪ (WRIST)																
Multi	MULTI ▪ 2 ▪ (NO)																
ARM-CRANE	YES ▪ (NO)																
BLADE	YES ▪ (NO)																
OFFSET	YES ▪ (NO)																
OFFSET Cylinder	FAIR ▪ Attn																
Piping	(YES) ▪ NO	Breaker only				▪ Multi				*1							
COMMENT Hリンク・Iリンク共にガタツキ大 H-LINK & I-LINKS: MUCH LOOSE スイベル油漏れあり SWIVEL: OIL LEAKING *1 ペダル固着のため不明 PEDAL: STUCK 																	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。