

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/12/23	MAKE	MITSUBISHI	MODEL	BS3F		
SERIAL	1S101089			STAMP	NOT FOUND		
HR METER	UNKNOWN	HR	SHOE	500LGP	YEAR	YR	
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP		NONE

ENGINE : MODEL		S/N	29350
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
OPERATION PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	PS • DD	DIFF. STEERING	YES • NO
Transmission	FAIR	Attn	
Travel	FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • FAIR • DIRTY		
Operator's Seat	FAIR • Attn	破損あり CUTS, BROKEN	
Glasses	FAIR	Attn	
AirCon	A/C • H/C • H only • C only • None		
BLADE & CYLINDERS			
BLADE	FAIR	Attn	
CYLD.(R)	FAIR • Attn	*1	
CYLD.(L)	FAIR	Attn	
TILT CYLD	FAIR	Attn	
ANGLE CYLD	FAIR	Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
COMMENT			
Ripper			
MULTI	S/S	Shanks	PCS
Ripper CYLD.	FAIR	Attn	
COMMENT			
ドーザーショベル DOZER-SHOVEL			
HRメーターなし HR METER: NOTHING			
*1 バケットシリンダー油漏れ小、メッキ剥がれ、アームシリンダーにじみあり			
*1 BUCKET CYLINDER: OIL LEAKING, COATING PEELED, ARM CYLINDER: OIL Oozing			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			
			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。