

INSPECTION SHEET 検品書

INSPECTION DATE	2025/12/16	MAKE	MOROOKA	MODEL	MST-800VD		
SERIAL	020108			STAMP	020108		
HR METER	410	HR	Odometer	km	YEAR	2021	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600R	TIRE	

ENGINE : MODEL		C4.4	S/N	44810552
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
OPERATION PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
TRANSMISSION & TRAVEL				
T/M TYPE	PS	DD	No. OF GEARS	2 GEAR(S)
Transmission	FAIR	Attn		
Travel	FAIR	Attn		
Swing	FAIR	Attn		
Articulate	FAIR	Attn		
FOOT BRAKE	FAIR	Attn		
PARKING BRAKE	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only None

MAIN FRAME	
MAIN FLAME	FAIR Attn
VESSEL	
VESSEL	FAIR Attn
REAR GATE TYPE	NORMAL L-GATE (FLAT)
REAR GATE	FAIR Attn
UNDERCARRIAGE: See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR WORN UNEVEN WEAR
COMMENT	
<div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。