

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/21	MAKE	YANMAR	MODEL	VIO30-2
SERIAL	22774B			STAMP	22774B
HR METER	4808	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	300R

ENGINE : MODEL S/N 75160

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	
Travel	FAIR	Attn	左へ蛇行する TOTTERING TO LEFT

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn 破れあり CUTS
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	傷小 SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

COMMENT

右トラックローラー1個不良あり
SOME RIGHT TRACK ROLLER: MALFUNCTION

BKT (STD / SLOPE / NARROW / SKELETON / OTHER ()

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only Multi *1

COMMENT

マフラー破れあり MUFFLER: MUCH CRACKED
キーシリンダー接触不良 IGNITION KEY CYLINDER: LOOSE CONNECTION
*1 配管ペダル固着気味 PEDAL: A LITTLE STUCK

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。