

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/12/25	MAKE	HITACHI	MODEL	KH150-2
SERIAL No.	PLATE : 192-0508	STAMP	192-508		
HR METER	5585	HR	SHOE	760FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · ☒ MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	☒ OK · NG	未確認 NOT CHECKED
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 6m × 2, 3m × 2	
BOOM TOTAL	28m	
TOP SHEAVE	YES · ☒ NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY	
Operator's Seat	☒ FAIR · Attn	破れ大 CUTS
Glasses	☒ FAIR · Attn	
AirCon	A/C · H/C · H only · C only · ☒ None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT		
WEIGHT	2	
HOOK	40t	
FREE FALL	☒ YES · NO	
LIFTER	YES · ☒ NO	
COMMENT		
CABドアノブ不良(閉めたら開かなくなる)		
DOOR KNOB: MALFUNCTION (UNABLE TO OPEN AFTER SHUTTING)		
バックストッパー曲がりあり SOME BACK STOPPER: BENT		
3mペンダント1本欠 ONE OF 3m PENDANTS: MISSING		
40tフック以外欠 OTHER HOOKS: MISSING		
@NARITA YARD		
TOP, BOTTOM, 6m × 1		
40t HOOK		
@SAKURA YARD		
BOOM: 6m × 1, 3m × 2		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。