

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/21	MAKE	HITACHI	MODEL	ZX50U-5A
SERIAL	HCMAEBA0C00052552		STAMP	HCMAEBA0C00052552	
HR METER	ERROR	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE		SHOE	400R	

ENGINE : MODEL		S/N
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	
MAIN PUMP		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
OPERATING SYSTEM		
Swing	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · <u>Attn</u>	増速S/W不良 HI/LO SWITCH: MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY	
Operator's Seat	<u>FAIR</u> · Attn	破れあり CUTS
Glasses	<u>FAIR</u> · Attn	
AirCon	A/C · H/C · H only · C only · <u>None</u>	
BOOM / ARM / BKT		
Boom	<u>FAIR</u> · Attn	
Boom Cylinder	<u>FAIR</u> · Attn	
Arm	<u>FAIR</u> · Attn	
Arm Cylinder	<u>FAIR</u> · Attn	
ATTACHMENT	<u>FAIR</u> · Attn	ガタあり LOOSE
BKT Cylinder	<u>FAIR</u> · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	YES · <u>NO</u>
BLADE	<u>YES</u> · NO
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	<u>FAIR</u> · Attn
Piping	<u>YES</u> · NO Breaker only · <u>Multi</u>
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。