

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

|                 |                                               |      |        |       |       |
|-----------------|-----------------------------------------------|------|--------|-------|-------|
| INSPECTION DATE | 2026/1/23                                     | MAKE | KUBOTA | MODEL | U-008 |
| SERIAL          | 13617                                         |      | STAMP  | 13617 |       |
| HR METER        | 1310                                          | HR   | YEAR   | YR    |       |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u> |      | SHOE   | 180R  |       |

|                                  |                                           |                            |            |        |
|----------------------------------|-------------------------------------------|----------------------------|------------|--------|
| <b>ENGINE : MODEL</b>            |                                           | D722                       | <b>S/N</b> | 4S0984 |
| Oil leakage                      | <u>FAIR</u> · Attn                        |                            |            |        |
| Blow-By                          | <u>FAIR</u> · Attn                        | A LITTLE · MIDDLE · SEVERE |            |        |
| Sound                            | <u>FAIR</u> · Attn                        |                            |            |        |
| Oil                              | <u>FAIR</u> · Attn                        |                            |            |        |
| Exhaust Color                    | <u>FAIR</u> · Attn                        |                            |            |        |
| US EPA                           | YES · <u>NO</u>                           |                            |            |        |
| <b>MAIN PUMP</b>                 |                                           |                            |            |        |
| Sound                            | <u>FAIR</u> · Attn                        |                            |            |        |
| Oil leakage                      | <u>FAIR</u> · Attn                        |                            |            |        |
| Power                            | <u>FAIR</u> · Attn                        |                            |            |        |
| <b>COOLING SYSTEM</b>            |                                           |                            |            |        |
| Radiator                         | <u>FAIR</u> · Attn                        |                            |            |        |
| Oil Cooler                       | <u>FAIR</u> · Attn                        |                            |            |        |
| <b>OPERATING SYSTEM</b>          |                                           |                            |            |        |
| Swing                            | <u>FAIR</u> · Attn                        |                            |            |        |
| Travel                           | <u>FAIR</u> · Attn                        |                            |            |        |
| <b>INTERIOR See Photos. 写真参照</b> |                                           |                            |            |        |
| INTERIOR COND.                   | CLEAN · <u>FAIR</u> · DIRTY               |                            |            |        |
| Operator's Seat                  | <u>FAIR</u> · Attn                        |                            |            |        |
| Glasses                          | FAIR · Attn                               |                            |            |        |
| AirCon                           | A/C · H/C · H only · C only · <u>None</u> |                            |            |        |
| <b>BOOM / ARM / BKT</b>          |                                           |                            |            |        |
| Boom                             | <u>FAIR</u> · Attn                        |                            |            |        |
| Boom Cylinder                    | <u>FAIR</u> · Attn                        |                            |            |        |
| Arm                              | <u>FAIR</u> · Attn                        |                            |            |        |
| Arm Cylinder                     | <u>FAIR</u> · Attn                        |                            |            |        |
| ATTACHMENT                       | <u>FAIR</u> · Attn                        |                            |            |        |
| BKT Cylinder                     | <u>FAIR</u> · Attn                        |                            |            |        |

|                                                                      |                                                    |
|----------------------------------------------------------------------|----------------------------------------------------|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                              |                                                    |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 3                                                  |
| <b>COMMENT</b>                                                       |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
| BKT                                                                  | <u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ( ) |
| Lever                                                                | LONG · <u>WRIST</u>                                |
| Multi                                                                | MULTI · 2 · <u>NO</u>                              |
| ARM-CRANE                                                            | YES · <u>NO</u>                                    |
| BLADE                                                                | <u>YES</u> · NO                                    |
| OFFSET                                                               | YES · <u>NO</u>                                    |
| OFFSET Cylinder                                                      | FAIR · Attn                                        |
| Piping                                                               | YES · <u>NO</u> Breaker only · Multi               |
| <b>COMMENT</b>                                                       |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
|                                                                      |                                                    |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 2                                                  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。