

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/12/8	MAKE	KATO	MODEL	HD512-6
SERIAL	KW?22E01HH0005676 SOME LETTER: UNREADABLE			STAMP	5676
HR METER	9461	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G

ENGINE : MODEL		4JJ1	S/N	208230
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only · None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	右側油漏れあり RIGHT CYLINDER: OIL LEAKING	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn	油漏れあり OIL LEAKING	
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn	にじみあり OIL OOZING	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
底板油汚れあり BOTTOM: OIL STAINS	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
E/Gフードヒンジ破損、フード外れあり	
ENGINE HOOD HINGES: BROKEN, ENGINE HOOD: COME OFF	
旋回モーター周りにじみあり AROUND SWING MOTOR: OIL OOZING	
ブーム下ホース破れあり	
SOME HOSES AROUND LOWER PART OF BOOM: A LITTLE DAMAGED	
P242F DPF異常表示あり	
"P242F" ERROR DISPLAY FOR DIESEL PARTICULATE FILTER SYSTEM	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。