

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2025/12/8	MAKE	TADANO	MODEL	AT-270-2
SERIAL No.	PLATE : 371132			STAMP : 371132	
HR METER	3035	HR	Odometer	8005	km
YEAR	YR				
CHASSIS	MODEL TKG-FRR90S1			No. 7057630	
SHOE				TIRE SIZE	215/70R17.5
MAX HIGHT	27			m	
MAX WEIGHT				200	kg

ENGINE : MODEL 4HK1 S/N 193161	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	YES ☒ NO
OPERATION PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	AT ☒ MT No. OF GEARS 6 GEARS
Transmission	☒ FAIR · Attn
4WD	4WD ☒ 2WD
Travel	☒ FAIR · Attn
Swing	☒ FAIR · Attn
FOOT BRAKE	☒ FAIR · Attn
PARKING BRAKE	☒ FAIR · Attn
BOOM	
No. of Section	4 SECTIONS
DERRICKING CYL.	☒ FAIR · Attn
EXTENSION CYL.	☒ FAIR · Attn

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn
Glasses	☒ FAIR · Attn
AirCon	☒ A/C · H/C · H only · C only · None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	FAIR · ☒ WORN · UNEVEN WEAR
COMMENT	
OUTRIGGERS X · ☒ H	
OUTRIGGERS COND.	FAIR · ☒ Attn *1
COMMENT	
バッテリーランプ点灯あり BATTERY WARNING LAMP: ON	
上物非常S/W入れないと動作しない	
UPPER PART: NEED TO OPERATE IN THE EMERGENCY MODE	
首振り用シリンダーサビあり BUCKET SWING CYLINDER: RUSTY	
*1 異常ランプ点灯、右後アウトリガーランプ点滅あり、非常S/W入れないと動作しない	
*1 WARNING LAMP: ON,	
REAR RIGHT OUTRIGGER LAMP: BLINKED,	
NEED TO OPERATE IN THE EMERGENCY MODE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。