

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/12/5	MAKE	KOMATSU	MODEL	D155AX-7	
SERIAL	90231			STAMP	KMT0D118E02090231	
HR METER	10157	HR	SHOE	650G	YEAR	YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER			CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL		6D140E-6	S/N	731472
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
OPERATION PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
TRANSMISSION & TRAVEL				
T/M TYPE	PS	DD	DIFF. STEERING	YES · NO
Transmission	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	破れあり CUTS	
Glasses	FAIR	Attn		
AirCon	A/C	H/C · H only · C only · None		
BLADE & CYLINDERS				
BLADE	FAIR	Attn		
CYLD.(R)	FAIR	Attn		
CYLD.(L)	FAIR	Attn		
TILT CYLD	FAIR	Attn		
ANGLE CYLD	FAIR	Attn		

UNDERCARRIAGE		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
COMMENT 右走行モーターにじみ、油汚れあり RIGHT TRAVEL MOTOR: OIL OOZING, OIL STAINS			
Ripper	MULTI • S/S	Shanks	2 PCS
Ripper CYLD.	FAIR • Attn		
COMMENT L03充電電圧低下エラー表示、バッテリーランプ点灯あり “L03” ERROR DISPLAY FOR LOW BATTERY VOLTAGE, BATTERY WARNING LAMP: ON			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。