

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/12/8	MAKE	KOMATSU	MODEL	PC228US-3E0
SERIAL	40746			STAMP	KMTPC161L02040746
HR METER	7863	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL 6D107E-1 S/N 26509455	
Oil leakage	FAIR • Attn
Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn
Oil	FAIR • Attn
Exhaust Color	FAIR • Attn
US EPA	YES • NO
MAIN PUMP	
Sound	FAIR • Attn
Oil leakage	FAIR • Attn
Power	FAIR • Attn
COOLING SYSTEM	
Radiator	FAIR • Attn
Oil Cooler	FAIR • Attn
OPERATING SYSTEM	
Swing	FAIR • Attn ガタあり SWING: LOOSE
Travel	FAIR • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • FAIR • DIRTY
Operator's Seat	FAIR • Attn ガタ、破れあり LOOSE, TORN
Glasses	FAIR • Attn ドアガラス割れあり DOOR GLASSES: BROKEN
AirCon	A/C • H/C • H only • C only • None
BOOM / ARM / BKT	
Boom	FAIR • Attn
Boom Cylinder	FAIR • Attn *1
Arm	FAIR • Attn ガタあり LOOSE
Arm Cylinder	FAIR • Attn
ATTACHMENT	FAIR • Attn ガタあり LOOSE
BKT Cylinder	FAIR • Attn 傷、にじみあり SCRATCHED, OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi *2
COMMENT	
ブーム背面ホースヒビあり	
SOME HOSES AROUND LOWER PART OF BOOM: CRACKED	
モニター画面の表示遅い(最初は暗くて少しずつ見えるようになる)	
MONITOR: LAGGY	
(MONITOR: DARK AT FIRST, BECOMING VISIBLE LITTLE BY LITTLE)	
E/G周りホースヒビあり SOME HOSE AROUND ENGINE: CRACKED	
リペイントあり REPAINTED	
E15エラー表示あり "E15" ERROR DISPLAY	
*1 右側にじみあり、左側油漏れ小	
*1 RIGHT CYLINDER: OIL OOZING, LEFT CYLINDER: OIL LEAKING	
*2 ペダル動き固い PEDAL: STIFF	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。