

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/1/20	MAKE	TADANO	MODEL	GR-250N-1
SERIAL No.	PLATE : FB4103		STAMP : TR256-0821		
HR METER	5912	HR	Odometer	78510	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE *1
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	

OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	

OPERATING SYSTEM		
Computer	OK	NG
Swing	FAIR	Attn
Travel	FAIR	Attn

TRANSMISSION		
Transmission	FAIR · Attn	
No. OF GEARS	4	GEARS
4WD	4WD · 6WD	

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN ・ FAIR ・ DIRTY	
Operator's Seat	FAIR ・ Attn	切れあり CUTS
Glasses	FAIR ・ Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・ None	

COMMENT

BOOM		
No. of Section	4	SECTIONS
CRACK/ENFORCEMENT	FAIR	▪ Attn
DERRICKING CYL.	FAIR	▪ Attn
EXTENSION CYL.	FAIR	▪ Attn
JIB	YES	▪ NO ジブ先端ヘコミあり TIP: DENT
JIB TYPE	STD	▪ (PWR)
MAIN & SUB WIRE	YES	▪ NO
FREE FALL	YES	▪ NO
HOOK	25t, BALL	

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)		3
TIRE WEAR	FAIR • WORN •	UNEVEN WEAR

COMMENT
右Fハブシール油漏れあり FRONT RIGHT HUB SEAL: OIL LEAKING

OUTRIGGERS				
OUTRIGGERS	(X)	▪	H	
OUTRIGGERS COND.	(FAIR)	▪	Attn	
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR L ▪ R

COMMENT	
左右E/Gサイドカバーなし ENGINE SIDE COVERS: MISSING	
親フック過巻装置不良	
OVERWINDING PREVENTION FOR MAIN HOOK: MALFUNCTION	
補巻ウインチモーターにじみあり	
AUXILIARY HOISTING WINCH MOTOR: OIL OOOZING	
*1 ホース切れあり BLOW-BY HOSE: CUT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。