

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/23	MAKE	CAT	MODEL	314CCR
SERIAL	NO PLATE		STAMP	CAT0314CCKHB00958	
HR METER	E4861 + 6147		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	にじみあり OIL OOZING
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり TORN
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	左右油漏れあり CYLINDERS: OIL LEAKING
Arm	FAIR · Attn	ガタあり LOOSE
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	傷、にじみあり SCRATCHED, OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT					
底板周りにじみあり BOTTOM: OIL OOZING					
BKT	STD / SLOPE / NARROW / SKELETON OTHER()				
Lever	LONG	▪	WRIST		
Multi	MULTI	▪	2	▪	NO
ARM-CRANE	YES	▪	NO		
BLADE	YES	▪	NO		
OFFSET	YES	▪	NO		
OFFSET Cylinder	FAIR	▪	Attn		
Piping	YES	▪	NO	Breaker only ▪ Multi	*1
COMMENT					
ブーム周りホースひび割れあり SOME HOSE AROUND BOOM: CRACKED					
エアクリーナー: CAB内にあり AIR CLEANER: PUTTING IN CAB					
HRメーターストップ HR METER: STOPPED					
*1 右側にじみあり RIGHT PIPE: OIL OOZING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。