

**INSPECTION SHEET 検品書**  
**CRAWLER CRANE クローラクレーン**

INSPECTION DATE	2025/12/25		MAKE	IHI		MODEL	CCH500			
SERIAL No.	PLATE : 26755			STAMP	26755					
HR METER	UNKNOW	HR	SHOE	760FLAT		YEAR	YR			
ENGINE : MODEL S/N				INTERIOR See Photos. 写真参照						
Oil leakage	FAIR	Attn			INTERIOR COND.	CLEAN	· FAIR	DIRTY		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE		Operator's Seat	FAIR	Attn	*1		
Sound	FAIR	Attn			Glasses	FAIR	Attn			
Oil	FAIR	Attn			AirCon	A/C	· H/C	· H only	· C only	None
Exhaust Color	FAIR	Attn			UNDERCARRIAGE : See Photos. 写真参照					
OPERATION PUMP				RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 2						
Sound	FAIR	Attn			COMMENT					
Oil leakage	FAIR	Attn			左右キャタ緩み大 TRACK LINKS: MUCH WORN					
Power	FAIR	Attn			WEIGHT	3				
COOLING SYSTEM				HOOK	50t, BALL					
Radiator	FAIR	Attn			FREE FALL	YES	· NO			
Oil Cooler	FAIR	Attn			LIFTER	YES	· NO			
OPERATING SYSTEM				COMMENT						
Computer	OK	· NG	未確認 NOT CHECKED		ガントリーシリンダー取り外し GANTRY CYLINDERS: PARTLY COME OFF					
Swing	FAIR	Attn			ウェイトボルト1本欠 SOME BOLT FOR COUNTER WEIGHT: MISSING					
Travel	FAIR	Attn			6mブームラチスパイプ曲がりあり SOME LATTICE PIPES OF 6m BOOM: BENT					
BOOM				*1 固定部分故障、破れあり MOUNTING PART: BROKEN, TORN						
MAIN BOOM	TOP, BOTTOM, 6m × 2			@NARITA YARD						
BOOM TOTAL	25m			BOOM: TOP, BOTTOM, 6m × 1						
TOP SHEAVE	YES	· NO			50t HOOK					
JIB				@SAKURA YARD						
TOWER				BOOM: 6m × 1						
				BALL HOOK						
				RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 1						

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。