

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/12/12	MAKE	HITACHI	MODEL	ZX200LCMH-5B
SERIAL	HCMDCKA8A00307848	STAMP	HCMDCKA8A00307848		
HR METER	6572	HR	YEAR		YR
CAB/CNP	ROPS CAB <input checked="" type="checkbox"/> CAB <input type="checkbox"/> ROPS CNP / CNP / NONE	SHOE	600FLAT		

ENGINE : MODEL 4HK1 S/N 765843			UNDERCARRIAGE : See Photos. 写真参照				
Oil leakage <input checked="" type="checkbox"/> Attn			RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3				
Blow-By <input checked="" type="checkbox"/> Attn A LITTLE - MIDDLE - SEVERE			COMMENT				
Sound <input checked="" type="checkbox"/> Attn							
Oil <input checked="" type="checkbox"/> Attn							
Exhaust Color <input checked="" type="checkbox"/> Attn							
US EPA YES <input checked="" type="checkbox"/> NO							
MAIN PUMP							
Sound <input checked="" type="checkbox"/> Attn			BKT	STD / SLOPE / NARROW / SKELETON <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> MAGNET)			
Oil leakage <input checked="" type="checkbox"/> Attn			Lever	LONG <input checked="" type="checkbox"/> WRIST <input type="checkbox"/>			
Power <input checked="" type="checkbox"/> Attn			Multi	MULTI <input checked="" type="checkbox"/> 2 <input type="checkbox"/> NO			
COOLING SYSTEM							
Radiator <input checked="" type="checkbox"/> Attn			ARM-CRANE	YES <input checked="" type="checkbox"/> NO			
Oil Cooler <input checked="" type="checkbox"/> Attn			BLADE	YES <input checked="" type="checkbox"/> NO			
OPERATING SYSTEM							
Swing <input checked="" type="checkbox"/> Attn ガタあり SWING: LOOSE			OFFSET	YES <input checked="" type="checkbox"/> NO			
Travel <input checked="" type="checkbox"/> Attn			OFFSET Cylinder	FAIR <input checked="" type="checkbox"/> Attn			
INTERIOR See Photos. 写真参照							
INTERIOR COND. CLEAN <input checked="" type="checkbox"/> FAIR <input type="checkbox"/> DIRTY			Piping	YES <input checked="" type="checkbox"/> NO Breaker only - Multi			
Operator's Seat <input checked="" type="checkbox"/> Attn			COMMENT				
Glasses <input checked="" type="checkbox"/> Attn			オイルフィルター近くホース油漏れ小				
AirCon <input checked="" type="checkbox"/> A/C - H/C - H only - C only - None			SOME HOSES AROUND OIL FILTER: OIL LEAKING				
BOOM / ARM / BKT							
Boom <input checked="" type="checkbox"/> Attn			コントロールバルブ油汚れあり AROUND CONTROL VALVE: OIL STAINS				
Boom Cylinder <input checked="" type="checkbox"/> Attn			エレベータCAB ELEVATOR CAB				
Arm <input checked="" type="checkbox"/> Attn			A/C動作しない A/C: NOT WORKING				
Arm Cylinder <input checked="" type="checkbox"/> Attn			マフラフィルタ警告、E/G異常警告表示あり				
ATTACHMENT <input checked="" type="checkbox"/> Attn			WARNINGS DISPLAY FOR DIESEL PARTICULATE FILTER & ENGINE				
BKT Cylinder <input checked="" type="checkbox"/> Attn メッキ剥がれあり COATING: PEELED							
			RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3				

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。