

INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2026/1/19	CATEGORY	自走式破砕機 MOBILE CRUSHER		
MAKE	KOMATSU		MODEL	BR100JG-1E	
SERIAL	1236		STAMP	NOT FOUND	
HR METER	3198	HR	Odometer	km	YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP NONE		SHOE	450G	TIRE

ENGINE	MODEL	S/N
Oil leakage	FAIR ・ Attn	Oil FAIR ・ Attn
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE Exhaust Color FAIR ・ Attn
Sound	FAIR ・ Attn	EPA YES ・ NO

CONDITION	FAIR ・ Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	TIRE WEAR	FAIR ・ WORN ・ UNEVEN WEAR
COMMENT			
リペイントあり REPAINTED			
コントロールバルブ周りホースにじみあり SOME HOSE AROUND CONTROL VALVE: OIL OOZING			
クラッシャーモーターホースにじみあり CRUSHER MOTOR HOSES: OIL OOZING			
磁選機モーター油漏れあり MAGNETIC SEPARATOR MOTOR: OIL LEAKING			
メーター不良 INDICATOR: MALFUNCTION			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。