

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2026/1/14	MAKE	KOBELCO	MODEL	SK60-3
SERIAL	LE-22169	STAMP		LE-22169	
HR METER	6905	HR	YEAR		YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE		450G	

ENGINE : MODEL S/N			UNDERCARRIAGE : See Photos. 写真参照		
Oil leakage	FAIR · Attn		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	COMMENT		
Sound	FAIR · Attn		左右シユーブッシュ割れあり SOME PIN BUSHES: MUCH CRACKED		
Oil	FAIR · Attn		スイベル付近油漏れあり AROUND SWIVEL: OIL LEAKING		
Exhaust Color	FAIR · Attn				
US EPA	YES · NO				
MAIN PUMP			BKT	STD / SLOPE / NARROW / SKELETON / OTHER( )	
Sound	FAIR · Attn		Lever	LONG · WRIST	
Oil leakage	FAIR · Attn		Multi	MULTI · 2 · NO	
Power	FAIR · Attn		ARM-CRANE	YES · NO	
COOLING SYSTEM			BLADE	YES · NO	
Radiator	FAIR · Attn		OFFSET	YES · NO	
Oil Cooler	FAIR · Attn		OFFSET Cylinder	FAIR · Attn	
OPERATING SYSTEM			Piping	YES · NO	Breaker only · Multi *2
Swing	FAIR · Attn		COMMENT		
Travel	FAIR · Attn		A/Cベルトなし、A/C不良 A/C: NO BELT, MALFUNCTION		
INTERIOR See Photos. 写真参照			E/Gストップが手動になっている		
INTERIOR COND.	CLEAN · FAIR · DIRTY		ENGINE STOPPER: NEED TO STOP BY HAND		
Operator's Seat	FAIR · Attn	破れ大 TORN	*1 ドアガラス一部、左右サイドガラス、Rガラス: プラ板		
Glasses	FAIR · Attn	*1	*1 SOME DOOR GLASS, SIDE GLASSES, & REAR GLASS: PLASTIC BOARDS		
AirCon	A/C · H/C · H only · C only · None		*2 右側ホースなし RIGHT HOSE: PARTLY MISSING		
BOOM / ARM / BKT					
Boom	FAIR · Attn				
Boom Cylinder	FAIR · Attn				
Arm	FAIR · Attn				
Arm Cylinder	FAIR · Attn	油漏れ小 OIL LEAKING			
ATTACHMENT	FAIR · Attn				
BKT Cylinder	FAIR · Attn	油漏れ小 OIL LEAKING	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。