

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2026/1/5	MAKE	KOBELCO	MODEL	LK300A
SERIAL	RL-03317			STAMP	NOT FOUND
HR METER	4496	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	少ない ENGINE OIL LEVEL: NOT ENOUGH
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS · DD	
Transmission	FAIR · Attn	1速だけ入る ABLE TO SHIFT INTO ONLY 1st GEAR
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	不良 MALFUNCTION
PARKING BRAKE	FAIR · Attn	不良 MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり CUTS
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
FRONT & CYLINDERS		
Arm	FAIR · Attn	
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	
Articulate	FAIR · Attn	*1

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · NO
ATTACHMENTS	
STD BKT	YES · OTHER
BLADE	YES · NO Piping for Tilt YES · NO
COMMENT	
シフトレバーが1速は入るが他は入らない	
SHIFT LEVER: UNABLE TO SHIFT IN ALL GEARS EXCEPT 1st GEAR	
*1 左シリンダー油漏れあり LEFT CYLINDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。