

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/12/22	MAKE	KATO	MODEL	KRM-13H
SERIAL No.	PLATE :	5911019	STAMP :	KR130-1019	
HR METER	5556	HR	Odometer	91987	km
TIRE SIZE	275/80R22.5	YEAR	YR		

ENGINE : MODEL S/N

Oil leakage	FAIR	Attn	下部にじみあり BOTTOM: OIL OOZING
Blow-By	FAIR	Attn	A LITTLE MIDDLE SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	白煙あり WHITE FUMES

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Computer	OK	NG	
Swing	FAIR	Attn	
Travel	FAIR	Attn	

TRANSMISSION

Transmission	FAIR	Attn	にじみあり OIL OOZING
No. OF GEARS	4	GEARS	
4WD	4WD	6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	傷あり CRACKED
AirCon	A/C	H/C	H only C only None

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	Attn	
DERRICKING CYL.	FAIR	Attn	
EXTENSION CYL.	FAIR	Attn	
JIB	YES	NO	*1
JIB TYPE	STD	PWR	
MAIN & SUB WIRE	YES	NO	
FREE FALL	YES	NO	
HOOK	13t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)		1
TIRE WEAR	FAIR • WORN • UNEVEN WEAR	

COMMENT

フェンダー上部穴あり TOP OF SOME FENDER: HUGE HOLE

OUTRIGGERS

OUTRIGGERS	X	H	
OUTRIGGERS COND.	FAIR	Attn	
Oil leakage (JACK CYL.)	FRONT	L R	REAR L R
Oil leakage (SLIDE CYL.)	FRONT	L R	REAR L R

COMMENT

伸縮レバー固着あり EXTENSION LEVER: STUCK	
*1 ジブシリンダー油漏れあり CYLINDER: OIL LEAKING	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。