

**INSPECTION SHEET 検品書**  
**CRAWLER CRANE クローラクレーン**

INSPECTION DATE	2025/12/25	MAKE	SUMITOMO	MODEL	SCX700-2C3
SERIAL No.	PLATE :	SC070-7219		STAMP	SC070-7219
HR METER	21763	HR	SHOE	760FLAT	YEAR
ENGINE : MODEL S/N				INTERIOR See Photos. 写真参照	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn			INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR · DIRTY
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE		Operator's Seat	<input checked="" type="radio"/> FAIR · Attn 破れあり CUTS
Sound	<input checked="" type="radio"/> FAIR · Attn			Glasses	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn			AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn			UNDERCARRIAGE : See Photos. 写真参照	
OPERATION PUMP				RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	
Sound	<input checked="" type="radio"/> FAIR · Attn			COMMENT	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn			WEIGHT	3
Power	<input checked="" type="radio"/> FAIR · Attn			HOOK	70t, 40t, 20t, BALL
COOLING SYSTEM				FREE FALL	<input checked="" type="radio"/> YES · NO
Radiator	<input checked="" type="radio"/> FAIR · Attn			LIFTER	<input checked="" type="radio"/> YES · NO
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn			COMMENT	
OPERATING SYSTEM				@NARITA YARD	
Computer	<input checked="" type="radio"/> OK · NG			BOOM: TOP, BOTTOM, 6m × 1, 3m × 1	
Swing	<input checked="" type="radio"/> FAIR · Attn			@SAKURA YARD	
Travel	<input checked="" type="radio"/> FAIR · Attn			BOOM: 9m × 2, 6m × 2, 3m × 2	
BOOM				HOOK: 40t, 20t, BALL	
MAIN BOOM	TOP, BOTTOM, 9m × 2, 6m × 3, 3m × 3			JIB: TOP, BOTTOM, 4.5m × 2, A SET OF PENDANTS	
BOOM TOTAL	54m			TOWER: TOP, BOTTOM, 6m × 3, 3m × 1, CAP (1.175m),	
TOP SHEAVE	<input checked="" type="radio"/> YES · NO			SWING LEVER, GUIDE ROLLER, A SET OF TOWER BRIDLES,	
JIB	18m			LATCH (HANGER SIDE), A SET OF PENDANTS	
TOP, BOTTOM, 4.5m × 2				RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	
TOWER	POST: 42m, TOWER JIB: 31m				
TOP, BOTTOM, 6m × 3, 3m × 1					

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。