

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/12/25	MAKE	TADANO	MODEL	GR-120N-2
SERIAL No.	PLATE : FD1877		STAMP : T005-0221		
HR METER	18925	HR	Odometer	135573	km
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	E/G上部油漏れあり UPPER PART: OIL LEAKING
Blow-By	FAIR ☒ Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	
Exhaust Color	FAIR ☒ Attn	
OPERATION PUMP		
Sound	FAIR ☒ Attn	
Oil leakage	FAIR ☒ Attn	
Power	FAIR ☒ Attn	
COOLING SYSTEM		
Radiator	FAIR ☒ Attn	
Oil Cooler	FAIR ☒ Attn	
OPERATING SYSTEM		
Computer	OK ☒ NG	
Swing	FAIR ☒ Attn	
Travel	FAIR ☒ Attn	公道走行不可 UNABLE TO RUN ON PUBLIC ROADS
TRANSMISSION		
Transmission	FAIR ☒ Attn	シフトアップしない UNABLE TO SHIFT UP
No. OF GEARS	3 GEARS	
4WD	4WD ☒ 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR ☒ DIRTY	
Operator's Seat	FAIR ☒ Attn	破れあり CUTS
Glasses	FAIR ☒ Attn	
AirCon	A/C ☒ H/C · H only · C only · None	
COMMENT		
CABスライドドア閉まり悪い SLIDE DOOR: MALFUNCTION TO SHUT		

BOOM				
No. of Section	6	SECTIONS		
CRACK/ENFORCEMENT	FAIR ☒ Attn			
DERRICKING CYL.	FAIR ☒ Attn			
EXTENSION CYL.	FAIR ☒ Attn			
JIB	YES ☒ NO			
JIB TYPE	STD ☒ PWR			
MAIN & SUB WIRE	YES ☒ NO			
FREE FALL	YES ☒ NO			
HOOK	12t, BALL			
UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)				3
TIRE WEAR		FAIR ☒ WORN · UNEVEN WEAR		
COMMENT				
Fバンパーヘコミあり FRONT BUMPER: DENT				
OUTRIGGERS				
OUTRIGGERS	X ☒ H			
OUTRIGGERS COND.	FAIR ☒ Attn	*1		
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R
COMMENT				
*1 左F縦シリンダーにじみあり FRONT LEFT JACK CYLINDER: OIL OOZING				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				
4				

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。