

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/12/22	MAKE	KOMATSU	MODEL	D65P-12E
SERIAL	62785			STAMP	D60P12-62785
HR METER	9503	HR	SHOE	950LGP	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

<table style="width: 100%;"> <tr> <td style="width: 50%;">ENGINE : MODEL</td> <td style="width: 50%;">S/N</td> </tr> <tr> <td>Oil leakage (FAIR) • Attn</td> <td></td> </tr> <tr> <td>Blow-By (FAIR) • Attn</td> <td>A LITTLE • MIDDLE • SEVERE</td> </tr> <tr> <td>Sound (FAIR) • Attn</td> <td></td> </tr> <tr> <td>Oil (FAIR) • Attn</td> <td></td> </tr> <tr> <td>Exhaust Color (FAIR) • Attn</td> <td></td> </tr> <tr> <td>US EPA YES • (NO)</td> <td></td> </tr> <tr> <td colspan="2">OPERATION PUMP</td> </tr> <tr> <td>Sound (FAIR) • Attn</td> <td></td> </tr> <tr> <td>Oil leakage (FAIR) • Attn</td> <td></td> </tr> <tr> <td>Power (FAIR) • Attn</td> <td></td> </tr> <tr> <td colspan="2">COOLING SYSTEM</td> </tr> <tr> <td>Radiator (FAIR) • Attn</td> <td></td> </tr> <tr> <td>Oil Cooler (FAIR) • Attn</td> <td></td> </tr> <tr> <td colspan="2">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE (PS) • DD</td> <td>DIFF. STEERING YES • (NO)</td> </tr> <tr> <td>Transmission (FAIR) • Attn</td> <td></td> </tr> <tr> <td>Travel (FAIR) • Attn</td> <td></td> </tr> <tr> <td colspan="2">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>INTERIOR COND. CLEAN • (FAIR) • DIRTY</td> <td></td> </tr> <tr> <td>Operator's Seat (FAIR) • Attn</td> <td></td> </tr> <tr> <td>Glasses (FAIR) • Attn</td> <td></td> </tr> <tr> <td>AirCon (A/C) • H/C • H only • C only • None</td> <td></td> </tr> <tr> <td colspan="2">BLADE & CYLINDERS</td> </tr> <tr> <td>BLADE (FAIR) • (Attn) *1</td> <td></td> </tr> <tr> <td>CYLD.(R) (FAIR) • Attn</td> <td></td> </tr> <tr> <td>CYLD.(L) (FAIR) • Attn</td> <td></td> </tr> <tr> <td>TILT CYLD (FAIR) • Attn</td> <td></td> </tr> <tr> <td>ANGLE CYLD (FAIR) • Attn</td> <td></td> </tr> </table>	ENGINE : MODEL	S/N	Oil leakage (FAIR) • Attn		Blow-By (FAIR) • Attn	A LITTLE • MIDDLE • SEVERE	Sound (FAIR) • Attn		Oil (FAIR) • Attn		Exhaust Color (FAIR) • Attn		US EPA YES • (NO)		OPERATION PUMP		Sound (FAIR) • Attn		Oil leakage (FAIR) • Attn		Power (FAIR) • Attn		COOLING SYSTEM		Radiator (FAIR) • Attn		Oil Cooler (FAIR) • Attn		TRANSMISSION & TRAVEL		T/M TYPE (PS) • DD	DIFF. STEERING YES • (NO)	Transmission (FAIR) • Attn		Travel (FAIR) • Attn		INTERIOR See Photos. 写真参照		INTERIOR COND. CLEAN • (FAIR) • DIRTY		Operator's Seat (FAIR) • Attn		Glasses (FAIR) • Attn		AirCon (A/C) • H/C • H only • C only • None		BLADE & CYLINDERS		BLADE (FAIR) • (Attn) *1		CYLD.(R) (FAIR) • Attn		CYLD.(L) (FAIR) • Attn		TILT CYLD (FAIR) • Attn		ANGLE CYLD (FAIR) • Attn		<table style="width: 100%;"> <tr> <td colspan="2">UNDERCARRIAGE See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td>4</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr> <td>Ripper</td> <td>MULTI • S/S Shanks PCS</td> </tr> <tr> <td>Ripper CYLD.</td> <td>FAIR • Attn</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2">*1 左プッシュアームとブレード間のボルト1個欠、補修跡あり</td> </tr> <tr> <td colspan="2">*1 SOME BOLT BETWEEN LEFT PUSH ARM & BLADE: MISSING, REPAIRED</td> </tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr><td colspan="2"> </td></tr> <tr> <td colspan="2">RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> </tr> <tr> <td colspan="2">4</td> </tr> </table>	UNDERCARRIAGE See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4	COMMENT														Ripper	MULTI • S/S Shanks PCS	Ripper CYLD.	FAIR • Attn	COMMENT		*1 左プッシュアームとブレード間のボルト1個欠、補修跡あり		*1 SOME BOLT BETWEEN LEFT PUSH ARM & BLADE: MISSING, REPAIRED																										RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4	
ENGINE : MODEL	S/N																																																																																																																		
Oil leakage (FAIR) • Attn																																																																																																																			
Blow-By (FAIR) • Attn	A LITTLE • MIDDLE • SEVERE																																																																																																																		
Sound (FAIR) • Attn																																																																																																																			
Oil (FAIR) • Attn																																																																																																																			
Exhaust Color (FAIR) • Attn																																																																																																																			
US EPA YES • (NO)																																																																																																																			
OPERATION PUMP																																																																																																																			
Sound (FAIR) • Attn																																																																																																																			
Oil leakage (FAIR) • Attn																																																																																																																			
Power (FAIR) • Attn																																																																																																																			
COOLING SYSTEM																																																																																																																			
Radiator (FAIR) • Attn																																																																																																																			
Oil Cooler (FAIR) • Attn																																																																																																																			
TRANSMISSION & TRAVEL																																																																																																																			
T/M TYPE (PS) • DD	DIFF. STEERING YES • (NO)																																																																																																																		
Transmission (FAIR) • Attn																																																																																																																			
Travel (FAIR) • Attn																																																																																																																			
INTERIOR See Photos. 写真参照																																																																																																																			
INTERIOR COND. CLEAN • (FAIR) • DIRTY																																																																																																																			
Operator's Seat (FAIR) • Attn																																																																																																																			
Glasses (FAIR) • Attn																																																																																																																			
AirCon (A/C) • H/C • H only • C only • None																																																																																																																			
BLADE & CYLINDERS																																																																																																																			
BLADE (FAIR) • (Attn) *1																																																																																																																			
CYLD.(R) (FAIR) • Attn																																																																																																																			
CYLD.(L) (FAIR) • Attn																																																																																																																			
TILT CYLD (FAIR) • Attn																																																																																																																			
ANGLE CYLD (FAIR) • Attn																																																																																																																			
UNDERCARRIAGE See Photos. 写真参照																																																																																																																			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4																																																																																																																		
COMMENT																																																																																																																			
Ripper	MULTI • S/S Shanks PCS																																																																																																																		
Ripper CYLD.	FAIR • Attn																																																																																																																		
COMMENT																																																																																																																			
*1 左プッシュアームとブレード間のボルト1個欠、補修跡あり																																																																																																																			
*1 SOME BOLT BETWEEN LEFT PUSH ARM & BLADE: MISSING, REPAIRED																																																																																																																			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)																																																																																																																			
4																																																																																																																			

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。