

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/12/23	MAKE	KOBELCO	MODEL	RK250-5
SERIAL No.	PLATE : EZ06-07221		STAMP : EZ03-7221		
HR METER	29992	HR	Odometer	61964	km
TIRE SIZE	445/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	にじみあり OIL OOZING
Blow-By	FAIR ☒ Attn	A LITTLE ☒ MIDDLE ☐ SEVERE
Sound	FAIR ☐ Attn	
Oil	FAIR ☐ Attn	
Exhaust Color	FAIR ☒ Attn	白煙あり WHITE FUMES
OPERATION PUMP		
Sound	FAIR ☐ Attn	
Oil leakage	FAIR ☐ Attn	
Power	FAIR ☐ Attn	
COOLING SYSTEM		
Radiator	FAIR ☐ Attn	
Oil Cooler	FAIR ☐ Attn	
OPERATING SYSTEM		
Computer	OK ☒ NG	
Swing	FAIR ☐ Attn	
Travel	FAIR ☒ Attn	*1
TRANSMISSION		
Transmission	FAIR ☒ Attn	ミッション滑りあり CLUTCH: SLIPPING
No. OF GEARS	3 GEARS	
4WD	4WD ☒ 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ☐ FAIR ☒ DIRTY	
Operator's Seat	FAIR ☐ Attn	
Glasses	FAIR ☐ Attn	
AirCon	A/C ☒ H/C ☐ H only ☐ C only ☐ None	
COMMENT		

BOOM				
No. of Section	4	SECTIONS		
CRACK/ENFORCEMENT	FAIR ☒ Attn			
DERRICKING CYL.	FAIR ☐ Attn			
EXTENSION CYL.	FAIR ☐ Attn			
JIB	YES ☒ NO			
JIB TYPE	STD ☐ PWR ☒			
MAIN & SUB WIRE	YES ☒ NO			
FREE FALL	YES ☒ NO			
HOOK	25t, BALL			
UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)				1
TIRE WEAR		FAIR ☒ WORN ☐ UNEVEN WEAR		
COMMENT				
OUTRIGGERS				
OUTRIGGERS	X ☒ H			
OUTRIGGERS COND.	FAIR ☒ Attn			
Oil leakage (JACK CYL.)	FRONT	L ☐ R	REAR	L ☐ R
Oil leakage (SLIDE CYL.)	FRONT	L ☐ R	REAR	L ☐ R
COMMENT				
コンピュータ正常3色灯赤点灯あり				
3-COLOR STATUS LAMP: RED LIGHTING				
*1 公道走行不可 UNABLE TO RUN ON PUBLIC ROADS				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。