

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/12/23	MAKE	HITACHI	MODEL	EX200-2
SERIAL	147-67485			STAMP	147-67485
HR METER	7144	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL 6BD1 S/N	
Oil leakage	FAIR • Attn
Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn
Oil	FAIR • Attn
Exhaust Color	FAIR • Attn
US EPA	YES • NO
MAIN PUMP	
Sound	FAIR • Attn
Oil leakage	FAIR • Attn
Power	FAIR • Attn
COOLING SYSTEM	
Radiator	FAIR • Attn
Oil Cooler	FAIR • Attn
OPERATING SYSTEM	
Swing	FAIR • Attn ガタ、ゴリゴリ感あり SWING: LOOSE, RATTLING
Travel	FAIR • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • FAIR • DIRTY
Operator's Seat	FAIR • Attn ガタ、穴、破れあり LOOSE, HOLE, CUT
Glasses	FAIR • Attn
AirCon	A/C • H/C • H only • C only • None
BOOM / ARM / BKT	
Boom	FAIR • Attn
Boom Cylinder	FAIR • Attn
Arm	FAIR • Attn
Arm Cylinder	FAIR • Attn
ATTACHMENT	FAIR • Attn ガタあり LOOSE
BKT Cylinder	FAIR • Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi
COMMENT	
旋回モーター周り油汚れあり AROUND SWING MOTOR: OIL STAINS	
作動油タンクにじみあり HYDRAULIC OIL TANK: OIL OOZING	
ブーム下ホース破れあり	
SOME HOSES AROUND LOWER PART OF BOOM: A LITTLE DAMAGED	
コントロールバルブにじみあり CONTROL VALVE: OIL OOZING	
作動油少ない HYDRAULIC OIL LEVEL: NOT ENOUGH	
ヒーター風量コントロールツマミ固着あり	
HEATER FAN SPEED CONTROL KNOB: STUCK	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。