

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |                   |             |
|-----------------|----------------------------------------|------|---------|-------------------|-------------|
| INSPECTION DATE | 2025/12/19                             | MAKE | KOMATSU | MODEL             | PC228US-3E0 |
| SERIAL          | 40038                                  |      | STAMP   | KMTPC161C02040038 |             |
| HR METER        | 8981                                   | HR   | YEAR    | YR                |             |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 600G              |             |

|                           |       |          |                            |          |
|---------------------------|-------|----------|----------------------------|----------|
| ENGINE : MODEL            |       | 6D107E-1 | S/N                        | 26503677 |
| Oil leakage               | FAIR  | Attn     |                            |          |
| Blow-By                   | FAIR  | Attn     | A LITTLE · MIDDLE · SEVERE |          |
| Sound                     | FAIR  | Attn     |                            |          |
| Oil                       | FAIR  | Attn     |                            |          |
| Exhaust Color             | FAIR  | Attn     |                            |          |
| US EPA                    | YES   | NO       |                            |          |
| MAIN PUMP                 |       |          |                            |          |
| Sound                     | FAIR  | Attn     |                            |          |
| Oil leakage               | FAIR  | Attn     |                            |          |
| Power                     | FAIR  | Attn     |                            |          |
| COOLING SYSTEM            |       |          |                            |          |
| Radiator                  | FAIR  | Attn     |                            |          |
| Oil Cooler                | FAIR  | Attn     |                            |          |
| OPERATING SYSTEM          |       |          |                            |          |
| Swing                     | FAIR  | Attn     |                            |          |
| Travel                    | FAIR  | Attn     |                            |          |
| INTERIOR See Photos. 写真参照 |       |          |                            |          |
| INTERIOR COND.            | CLEAN | FAIR     | DIRTY                      |          |
| Operator's Seat           | FAIR  | Attn     | 破れあり TORN                  |          |
| Glasses                   | FAIR  | Attn     |                            |          |
| AirCon                    | A/C   | H/C      | H only                     | C only   |
|                           |       |          |                            | None     |
| BOOM / ARM / BKT          |       |          |                            |          |
| Boom                      | FAIR  | Attn     | ガタあり LOOSE                 |          |
| Boom Cylinder             | FAIR  | Attn     |                            |          |
| Arm                       | FAIR  | Attn     | パッチあり PATCHED              |          |
| Arm Cylinder              | FAIR  | Attn     |                            |          |
| ATTACHMENT                | FAIR  | Attn     |                            |          |
| BKT Cylinder              | FAIR  | Attn     |                            |          |

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。