

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/1/19	MAKE	KATO	MODEL	KR-35H-V
SERIAL No.	PLATE :	2310221	STAMP :	KR352-0221	
HR METER	26032	HR	Odometer	2364	km
TIRE SIZE	445/95R25	YEAR	YR		

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	E/Gヘッドにじみあり CYLINDER HEAD: OIL OOZING
Blow-By	FAIR ☒ Attn	A LITTLE ☒ MIDDLE ☐ SEVERE ☐
Sound	FAIR ☒ Attn	
Oil	FAIR ☒ Attn	
Exhaust Color	FAIR ☒ Attn	
OPERATION PUMP		
Sound	FAIR ☒ Attn	
Oil leakage	FAIR ☒ Attn	
Power	FAIR ☒ Attn	
COOLING SYSTEM		
Radiator	FAIR ☒ Attn	
Oil Cooler	FAIR ☒ Attn	
OPERATING SYSTEM		
Computer	OK ☒ NG ☐	
Swing	FAIR ☒ Attn	
Travel	FAIR ☒ Attn	
TRANSMISSION		
Transmission	FAIR ☒ Attn	*1
No. OF GEARS	4 GEARS	
4WD	4WD ☒ 6WD ☐	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ☐ FAIR ☒ DIRTY ☐	
Operator's Seat	FAIR ☒ Attn	
Glasses	FAIR ☒ Attn	
AirCon	A/C ☒ H/C ☐ H only ☐ C only ☐ None ☐	
COMMENT		

BOOM					
No. of Section	5	SECTIONS			
CRACK/ENFORCEMENT	FAIR ☒ Attn				
DERRICKING CYL.	FAIR ☒ Attn				
EXTENSION CYL.	FAIR ☒ Attn				
JIB	YES ☒ NO ☐				
JIB TYPE	STD ☐ PWR ☒				
MAIN & SUB WIRE	YES ☒ NO ☐				
FREE FALL	YES ☒ NO ☐				
HOOK	35t, 19t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)					2
TIRE WEAR		FAIR ☒ WORN ☐ UNEVEN WEAR ☐			
COMMENT					
OUTRIGGERS					
OUTRIGGERS	X ☐ H ☒				
OUTRIGGERS COND.	FAIR ☒ Attn	*2			
Oil leakage (JACK CYL.)	FRONT	L ☐ R ☐	REAR	L ☐ R ☐	
Oil leakage (SLIDE CYL.)	FRONT	L ☐ R ☐	REAR	L ☒ R ☐	
COMMENT					
右サイド後方上部へコミあり REAR RIGHT SIDE OF UPPER PART: DENT					
*1 ミッションゲージにじみあり TRANSMISSION GAUGE: OIL OOZING					
*2 右F縦シリンダーロッド傷、にじみあり					
*2 FRONT RIGHT JACK CYLINDER: SCRATCHED, OIL OOZING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。