

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/12/22	MAKE	TADANO	MODEL	GR-120N-1
SERIAL No.	PLATE : FD0079		STAMP : TR120-0079		
HR METER	8794	HR	Odometer	55790	km
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR (Attn)	E/G上部にじみあり UPPER PART: OIL OOZING
Blow-By	FAIR (Attn)	(A LITTLE) ・ MIDDLE ・ SEVERE
Sound	(FAIR) ・ Attn	
Oil	(FAIR) ・ Attn	
Exhaust Color	(FAIR) ・ Attn	

OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR - Attn	
Oil Cooler	FAIR - Attn	

OPERATING SYSTEM		
Computer	OK	NG
Swing	FAIR	Attn
Travel	FAIR	Attn

TRANSMISSION		
Transmission	FAIR • Attn	
No. OF GEARS	3 GEARS	
4WD	4WD • 6WD	

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり HUGE CUTS
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only C only None

COMMENT

BOOM		
No. of Section	6	SECTIONS
CRACK/ENFORCEMENT	☐ FAIR ▪ Attn	
DERRICKING CYL.	☐ FAIR ▪ Attn	
EXTENSION CYL.	☐ FAIR ▪ Attn	
JIB	☐ YES ▪ NO	
JIB TYPE	STD ▪ ☐ PWR	
MAIN & SUB WIRE	☐ YES ▪ NO	
FREE FALL	YES ▪ ☐ NO	
HOOK	4.9t, BALL	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	3
TIRE WEAR (FAIR • WORN • UNEVEN WEAR)	

COMMENT	

OUTRIGGERS				
OUTRIGGERS	(X)	▪	H	
OUTRIGGERS COND.	(FAIR)	▪	Attn	
Oil leakage (JACK CYL.)	FRONT	L	▪ R	REAR L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪ R	REAR L ▪ R

COMMENT	
作動油タンクホースにじみあり HYDRAULIC OIL TANK HOSE: OIL OOOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。