

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/12/22	MAKE	TADANO	MODEL	GR-120NL-2
SERIAL No.	PLATE : FD1708		STAMP : T005-0071		
HR METER	21390	HR	Odometer	170465	km
TIRE SIZE	275/80R22.5		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR (Attn)	上部油漏れあり UPPER PART: OIL LEAKING
Blow-By	(FAIR) ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	(FAIR) ・ Attn	
Oil	(FAIR) ・ Attn	
Exhaust Color	(FAIR) ・ Attn	

OPERATION PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	

OPERATING SYSTEM

Computer	OK	NG
Swing	FAIR	Attn
Travel	FAIR	Attn

TRANSMISSION

Transmission	FAIR · Attn	
No. OF GEARS	3	GEARS
4WD	4WD · 6WD	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	

COMMENT

BOOM

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	▪ Attn	
DERRICKING CYL.	FAIR	▪ Attn	
EXTENSION CYL.	FAIR	▪ Attn	
JIB	YES	▪ NO	
JIB TYPE	STD	▪ PWR	
MAIN & SUB WIRE	YES	▪ NO	
FREE FALL	YES	▪ NO	
HOOK	12t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)		3
TIRE WEAR	FAIR • WORN • UNEVEN WEAR	

COMMENT

OUTRIGGERS

OUTRIGGERS	☒ X	▪	H			
OUTRIGGERS COND.	☒ FAIR	▪	Attn			
Oil leakage (JACK CYL.)	FRONT	L	▪	R	REAR	L ▪ R
Oil leakage (SLIDE CYL.)	FRONT	L	▪	R	REAR	L ▪ R

COMMENT

[illegible]

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
---	----------

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。