

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/12/24	MAKE	HITACHI	MODEL	ZW180
SERIAL	RYU4GD00J00005511			STAMP	S63-05511
HR METER	8028	HR	Odometer	23903	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5-25

ENGINE : MODEL QSB6.7 S/N 26585921	
Oil leakage	☒ FAIR • Attn
Blow-By	☒ FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	☒ FAIR • Attn
Oil	☒ FAIR • Attn
Exhaust Color	☒ FAIR • Attn
US EPA	☒ YES • NO
OPERATION PUMP	
Sound	☒ FAIR • Attn
Oil leakage	☒ FAIR • Attn
Power	☒ FAIR • Attn
COOLING SYSTEM	
Radiator	☒ FAIR • Attn
Oil Cooler	☒ FAIR • Attn
TRANSMISSION & TRAVEL	
T/M TYPE	☒ PS • DD
Transmission	☒ FAIR • Attn
Travel	☒ FAIR • Attn
FOOT BRAKE	☒ FAIR • Attn
PARKING BRAKE	☒ FAIR • Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • ☒ FAIR • DIRTY
Operator's Seat	☒ FAIR • Attn
Glasses	☒ FAIR • Attn
AirCon	☒ A/C • H/C • H only • C only • None
FRONT & CYLINDERS	
Arm	☒ FAIR • ☒ Attn 左右シリンダー油漏れあり CYLINDERS: OIL LEAKING
Bell crank	☒ FAIR • Attn
Bucket	☒ FAIR • Attn
Articulate	☒ FAIR • Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR • ☒ WORN • UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☒ COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	☒ YES • NO
ATTACHMENTS	
STD BKT	☒ YES • OTHER
BLADE	YES • ☒ NO Piping for Tilt ☒ YES • NO *1
COMMENT	
*1 左右配管欠 PIPES: MISSING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。