

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/12/11	MAKE	KOMATSU	MODEL	PC200-8N1
SERIAL	357369		STAMP	KMTPC197J02357369	
HR METER	11361	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		6D107E-1	S/N	26617064
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	破れあり CUTS	
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only
None				
BOOM / ARM / BKT				
Boom	FAIR	Attn	補修跡あり REPAIRED	
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	*1	
BKT Cylinder	FAIR	Attn	傷あり SCRATCHED	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
COMMENT 右トラックローラーガタあり SOME RIGHT TRACK ROLLERS: LOOSE		
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG ▪ (WRIST)	
Multi	(MULTI) ▪ 2 ▪ NO	
ARM-CRANE	(YES) ▪ NO	
BLADE	YES ▪ (NO)	
OFFSET	YES ▪ (NO)	
OFFSET Cylinder	FAIR ▪ Attn	
Piping	YES ▪ (NO)	Breaker only ▪ Multi
COMMENT *1 サビ大、補修跡、Hリンクサビあり *1 MUCH RUSTY, REPAIRED, H-LINK: RUSTY		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。