

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2026/1/21		MAKE	S-MAC		MODEL	NXH97				
SERIAL No.	PLATE : 00076			STAMP :		NOT FOUND					
HR METER	852	HR	Odometer	-		km	YEAR	YR			
CHASSIS	MODEL -			No.			-				
SHOE				TIRE SIZE		15 × 5					
MAX HIGHT	9.7 m			MAX WEIGHT		250 kg					
ENGINE : MODEL S/N					INTERIOR See Photos. 写真参照						
Oil leakage	FAIR	Attn				INTERIOR COND.	CLEAN		FAIR	DIRTY	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE			Operator's Seat	FAIR	Attn			
Sound	FAIR	Attn				Glasses	FAIR	Attn			
Oil	FAIR	Attn				AirCon	A/C	H/C	H only	C only	None
Exhaust Color	FAIR	Attn				UNDERCARRIAGE : See Photos. 写真参照					
US EPA	YES	NO				RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
OPERATION PUMP						TIRE WEAR FAIR · WORN · UNEVEN WEAR					
Sound	FAIR	Attn				COMMENT					
Oil leakage	FAIR	Attn				後部タイヤ2本とも劣化あり REAR TIRES: DETERIORATED					
Power	FAIR	Attn									
COOLING SYSTEM						OUTRIGGERS X · H *1					
Radiator	FAIR	Attn				OUTRIGGERS COND.	FAIR	Attn			
Oil Cooler	FAIR	Attn				COMMENT					
TRANSMISSION & TRAVEL						リペイントあり REPAINTED					
T/M TYPE	AT	·	MT			No. OF GEARS	GEARS				
Transmission	FAIR	Attn				上部操作安全ペダル戻り悪い					
4WD	4WD	·	2WD				SAFETY PEDAL AT BUCKET: HARD TO RETURN				
Travel	FAIR	Attn				*1 側部アウトリガーあり W/SIDE OUTRIGGERS					
Swing	FAIR	Attn									
FOOT BRAKE	FAIR	Attn									
PARKING BRAKE	FAIR	Attn									
BOOM											
No. of Section	- SECTIONS										
DERRICKING CYL.	FAIR	Attn									
EXTENSION CYL.	FAIR	Attn									
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)										3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。