

INSPECTION SHEET 検品書
CARRY DUMP キャリーダンプ

INSPECTION DATE	2026/1/7	MAKE	YANMAR	MODEL	C30R		
SERIAL	01809			STAMP	NOT FOUND		
HR METER	E823	HR	Odometer	km	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	320R	TIRE	

ENGINE : MODEL		S/N		08948	
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
OPERATION PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
TRANSMISSION & TRAVEL					
T/M TYPE	PS	DD	No. OF GEARS		2 GEARS
Transmission	FAIR	Attn			
Travel	FAIR	Attn	右走行レバー重い RIGHT TRAVEL LEVER: STIFF		
Swing	FAIR	Attn			
Articulate	FAIR	Attn			
FOOT BRAKE	FAIR	Attn	効きが悪い BRAKE: LOOSE		
PARKING BRAKE	FAIR	Attn	効きが悪い BRAKE: LOOSE		
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN · FAIR ·		DIRTY		
Operator's Seat	FAIR	Attn			
Glasses	FAIR	Attn			
AirCon	A/C · H/C · H only · C only · None				

MAIN FRAME					
MAIN FLAME		FAIR	▪	Attn	
VESSEL					
VESSEL		FAIR	▪	Attn	
REAR GATE TYPE		NORMAL	▪	L-GATE (FLAT)	
REAR GATE		FAIR	▪	Attn	
UNDERCARRIAGE: See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
TIRE WEAR		FAIR	▪	WORN ▪ UNEVEN WEAR	
COMMENT					
ライト、ウインカー不良 HEAD LIGHTS & BLINKERS: MALFUNCTION リペイントあり REPAINTED HRメーターストップ HR METER: STOPPED					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。